

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,928,572 B2
DATED : August 9, 2005
INVENTOR(S) : Thomas D. Fletcher et al.

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 9.

Line 52, "to signal at the a clock" should be -- to the signal at a clock --;

Column 10.

Line 57, "delay block provide" should be -- delay block to provide --.

Signed and Sealed this

Seventh Day of March, 2006



JON W. DUDAS
Director of the United States Patent and Trademark Office